PRELIMINARY SUMMARY OF MAP ACTIONS

Community: CROWN POINT, CITY OF Community No: 180128

To assist your community in maintaining the Flood Insurance Rate Map (FIRM), we have summarized below the previously issued Letter of Map Change (LOMC) actions (i.e., Letters of Map Revision (LOMRs) and Letters of Map Amendment (LOMAs)) that will be affected by the preparation of the enclosed revised FIRM panel(s).

1. LOMCs Incorporated

The modifications effected by the LOMCs listed below have been reflected on the Preliminary copies of the revised FIRM panels. In addition, these LOMCs will remain in effect until the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
			NO CASES RECORDED		

2. LOMCs Not Incorporated

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because of scale limitations or because the LOMC issued had determined that the lot(s) or structure(s) involved were outside the Special Flood Hazard Area, as shown on the FIRM. These LOMCs will be revalidated free of charge 1 day after the revised FIRM becomes effective through a single revalidation letter that reaffirms the validity of the previous LOMCs.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	98-05-5946A	09/18/1998	BEAVER DAM VILLAGE, SECTON 1-A, UNIT 4-2 - 341 DAHLGREN DRIVE	1801280005C	18126C0261E
LOMA	98-05-6788A	09/18/1998	BEAVER DAM VILLAGE, SECTION 1-A, UNIT 2-1 - 353 WEST DAHLGEN DRIVE	1801280005C	18126C0261E
LOMA	99-05-662A	11/25/1998	BEAVER DAM VILLAGE - UNIT 2-3, SECTION 1-A - 361 WEST DAHLGREN DRIVE	1801280005C	18126C0261E
LOMA	99-05-1036A	12/11/1998	BEAVER DAM VILLAGE, SECTION 1A - UNIT 4-1 - 345 DAHLGREN DRIVE	1801280005C	18126C0261E
LOMA	02-05-4723A	10/16/2002	BROOKSIDE PHASE 4, LOT 33; 1262 CENTER ROSS ROAD	1801280005C	18126C0262E
LOMA	05-05-4270A	09/27/2005	CARROLL'S 1ST BEAVER DAM ADDITION, LOT 26 408 WEST ANDERSON COURT	1801280005C	18126C0261E
LOMR-F	06-05-B497A	05/04/2006	2323 EAST 101ST AVENUE PORTION OF SECTION 2, T34N, R8W (IN)	1801260105B 1801260115B 1801260120B	18126C0266E
LOMA	06-05-BI40A	05/12/2006	PENN OAK UNIT 4 SUBDIV PORTION OF SECTION 9, T34N, R8W (OH)	1801260115B	18126C0266E

12/4/2008 Page 1 of 2

PRELIMINARY SUMMARY OF MAP ACTIONS

Community: CROWN POINT, CITY OF Community No: 180128

3. LOMCs Superseded

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because they are being superseded by new detailed flood hazard information or the information available was not sufficient to make a determination. The reason each is being superseded is noted below. These LOMCs will no longer be in effect when the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Reason Determination Will be Superseded
			NO CASES RECORDED	

- 1. Insufficient information available to make a determination.
- 2. Lowest Adjacent Grade and Lowest Finished Floor are below the proposed Base Flood Elevation.
- 3. Lowest Ground Elevation is below the proposed Base Flood Elevation.
- 4. Revised hydrologic and hydraulic analyses.
- 5. Revised topographic information.

4. LOMCs To Be Redetermined

The LOMCs in Category 2 above will be revalidated through a single revalidation letter that reaffirms the validity of the determination in the previously issued LOMC. For LOMCs issued for multiple lots or structures where the determination for one or more of the lots or structures has changed, the LOMC cannot be revalidated through this administrative process. Therefore, we will review the data previously submitted for the LOMC requests listed below and issue a new determination for the affected properties after the effective date of the revised FIRM.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
			NO CASES RECORDED		

12/4/2008 Page 2 of 2